

BORDEN PARISH HALL REPORT SEPTEMBER 2025

1. The subsidence in the Hall driveway is not due to water as the lifting pump cover was raised and the chamber inspected.
2. I am obtaining a quote to reinstate the paving near the lifting pump and the small area in the driveway. I am still looking at the ownership situation.
3. It has been noted that the water pressure in the Hall toilets is very low. However the pressure in the kitchen is normal. I will get a contractor to find the cause of the problem.
4. The above events have delayed Hall projects such as Blinds being replaced and floor being resurfaced.

John Hepburn

Borden Parish Hall Chairman